AG 6D-22
Calibration after battery swap

After inserting battery hold on the tool for one second

Release grip from SensTech deadman's

Grab again and turn switch on, SensTech is now calibrated

AG 6D-22 | SensTech calibration